





# Show Contours

Enable command panel




Display on/OFF

Display on/OFF

Active Contour


# Multiple usage of TX for large targets TX1



Program target

TX1 target


# Multiple usage of TX for large targets TX2



Program target

TX2 target


# Multiple usage of TX for large targets TX3



Program target

TX3 target


# Multiple usage of TX for large targets coverage of TX1



Program target

TX1 target


# Multiple usage of TX for large targets coverage of TX2



Program target

TX2 target

# Multiple usage of TX for large targets coverage of TX3



Program target

TX3 target